Mezzanine Inspection Report REVISION 3

Date: 03/11/2015 Station Name: Farragut West – C03 Mezzanine #: 038 Completed By: Mike Butler

Summary

Video scoping and pull string installation completed for communication ducts for the faregate arrays. Video scoping completed for power ducts for the faregate arrays as well. Video scoping was partially completed in the power run from the kiosk to the AFC panel due to access issues at 90-degree bends which do not have an associated handhole. There are a total of 2 90-degree bends between the kiosk and AFC panel. During scoping PLNT masons opened the mezzanine floor at the first 90-degree bend coming from the kiosk. The duct was exposed, but there was no handhole. Pull string was not installed in the power run from the kiosk to AFC panel. AFC panel is located in Cleaners and Water Service Room 201.

Scanning was completed at this mezzanine. A proposed duct is recommended to run from the southeast face of the kiosk and continue parallel to the existing ducts, hugging as close to the wall as possible. Handholes are proposed at the bend locations. The duct will transition from duct to overhead conduit at the third handhole, adjacent to the existing recycle bins. The proposed conduit will run vertically up the side wall to the core drill location where it will pass through the wall into Room 201. Once inside Room 201, the conduit will run along the inside wall towards the AFC Panel.

Refer to photos and drawings for further information.

Photos and drawings are for reference purposes only; see new schematic drawing/proposed pathway on last page.

Scoping of Faregate Array(s)				
Task	Yes/No	Notes		
Communications Duct - Upper Faregate Array (8 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Farragut West 3inch Upper Comm Faregate.avi file.		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	3" duct less than 15 wires		
Communications Duct - Lower Faregate Array (3 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Farragut West 3inch Lower Comm Faregate.avi & WMATA Farragut West 6inch Lower Comm Faregate.avi files.		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	3" duct less than 15 wires		
Power Duct - Upper Faregate Array (8 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Farragut West 6inch Upper Power Faregate.avi file.		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" duct less than 15 wires		
Power Duct - Lower Faregate Array (3 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Farragut West 6inch Lower Power Faregate.avi & WMATA Farragut West 3inch Lower Power Faregate.avi files.		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" duct less than 15 wires		

Scoping of Power Duct - Kiosk to AFC Panel			
Task	Yes/No	Notes	
Kiosk to 90-degree bend (Distance: 50')			
Was video scoping completed for the entire duct / conduit run?	No	Refer to WMATA Farragut West (East) 6inch Left Power Feed.avi & WMATA Farragut West (East) 6inch Right Power Feed files.	
Was pull string installed?	No		
Were there any obstructions or blockages? Provide details of type and specific location.	Yes	No handhole access to complete scoping and pull string installation	
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	No	6"duct less than 15 wires	
90-degree bend to 90-degree bend (Distance: 32')			
Was video scoping completed for the entire duct / conduit run?	No		
Was pull string installed?	No		
Were there any obstructions or blockages? Provide details of type and specific location.	Yes	No handhole access to complete scoping and pull string installation	
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	N/A		
90-degree bend to AFC Panel (Distance: 10')	•		
Was video scoping completed for the entire duct / conduit run?	No		
Was pull string installed?	No		
Were there any obstructions or blockages? Provide details of type and specific location.	Yes	No handhole access to complete scoping and pull string installation	
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	N/A		
	Observation	ns / Issues / Next Steps	
Total length of existing power run from Kiosk to AFC Proposed power run from Kiosk to AFC Panel is 115			
		Sign Off	
GFP Representa	ntive	Sign Off WMATA PRGM	
Name: Mike Butler			
Signature:			
. 17			
Date: 07/01/2015			

Photo #1: Existing and Proposed Duct from Kiosk




Photo #2: Existing and Proposed Duct/Conduit on mezzanine floor




Photo #3: Existing duct on mezzanine floor



Photo #4: Proposed Conduit from core drill location feeding AFC panel SEMA in room 201




Photo #5: Existing Duct and Proposed Conduit feeding AFC panel SEMA in room 201



