Mezzanine Inspection Report (Scoping)				
Date: 12/15/14	Station Name: D10 - Deanwood	Mezzanine #: 065	Completed By: Mike Butler	

## Summary

All video scoping and pull string installation was completed successfully at this mezzanine. The following work was completed:

- Video scoping and pull string installation completed for comm. duct in upper faregate array.
- Video scoping and pull string installation completed for comm. duct in lower faregate array.
- Video scoping completed for power duct in upper faregate array.
- Video scoping completed for power duct in lower faregate array.
- Pull string installation completed in power conduit between Kiosk and AFC Panel.


Scoping of Faregate Array(s)				
Task	Yes/No	Notes		
Communications Duct – Upper Faregate Array (4 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Deanwood 6inch Upper Comm Video.avi"		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 12 wires.		
Communications Duct - Lower Faregate Array (3 g	ates)			
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Deanwood 6inch Lower Comm Video.avi"		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 12 wires.		
Power Duct - Upper Faregate Array (4 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Deanwood 6inch Upper Power Video.avi"		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 15 wires.		
Power Duct - Lower Faregate Array (3 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Deanwood 6inch Lower Power Video.avi"		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 15 wires.		


Scoping of Power Duct - Kiosk to AFC Panel					
	Task	Yes/No		Notes	
Kiosk to AFC Par	nel (Distance: 130')				
Was video scopii conduit run?	ng completed for the entire duct /	No	Scoping of conduit	not required.	
Was pull string in	stalled?	Yes			
Were there any o details of type and	bstructions or blockages? Provide d specific location.	No			
Is the duct / condi- details about the number of wires.	uit at capacity? Provide additional dimensions of duct / conduit and	No	2" rigid conduit with	n less than 8 wires.	
		T			
		l			
Observations / Issues / Next Steps					
	of power conduit between Kiosk and ed photos and drawings for detailed		s 130'.		
Cian Off					
	Sign Off  GFP Representative WMATA PRGM				GM
Name:	Mike Butler				
Signature:	M.zur				
Date:	03/05/15				

Photo #1 – Existing power conduit on mezzanine floor.



Photo #2 – Existing power conduit feeds to AFC Panel.





ON THIS DRAWING BY THE X DRAWN THRU THE MACHINE

FOR REFRENCE DRAWINGS USED SEE SUPPORT DOCUMENTATION

FOR AS BUILT CONDITIONS SEE SHEET. 2.

IGE FOR THIS MEZZANINE.

VIEW A-A

REVISIONS

DATE APVA.

DESCRIPTION

-ZINSTALLATION PLAN

CONTRACT NUMBER CUBIC WESTERN DATA 2 Z 00 7 A A subsidiary of Cubic Corporation 5650 KEARNY MESA ROAD • POST OFFICE BOX 80787 • SAN DIEGO, CA 92138 DEANWOOD STATION AFC MACHINES DESIGN ACTIVITY APPROVAL DRAWING NUMBER Wylie D. Porell 10-26-7 726-0405

## Mezzanine Inspection Report Date: 02/19/15 Station Name: D11 Cheverly Mezzanine #: 066 Completed By: Mike Butler Summary

100% completion of video scoping and pull string installation. Completed works includes:

- Video scoping and pull string installation completed for Upper and Lower Faregate communication ducts; respective power duct were also video scoped.
- Video scoping and pull string installation completed in power duct between Kiosk, Handhole 1, Handhole 2 and AFC Panel.

Refer to drawings and photos for detailed layout.

Scoping of Faregate Array(s)				
Task	Yes/No	Notes		
Communications Duct - Upper Faregate Array (3 g	ates)			
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Cheverly Station Upper Comm 6 inch duct.avi"		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 10 wires.		
Communications Duct - Lower Faregate Array (3 g	ates)			
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Cheverly Station Lower Comm 3 inch duct.avi"		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	3" walker duct with less than 10 wires.		
Power Duct - Upper Faregate Array (3 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Cheverly Station Upper Power 6 inch duct.avi"		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 10 wires.		
Power Duct - Lower Faregate Array (3 gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to "WMATA Cheverly Station Lower Power 6 inch duct.avi"		
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	6" walker duct with less than 10 wires.		

Scoping of Power Duct - Kiosk to AFC Panel				
Task Yes/No Notes				
Kiosk to Handhole 1 (Distance: 48')				
Was video scoping completed for the entire duct / conduit run?	Yes	Refer to "WMATA Cheverly 6inch Power HH1 to Kiosk.avi"		
Was pull string installed?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	No	6" walker duct with less than 12 wires.		
Handhole 1 to Handhole 2 (Distance: 90')				
Was video scoping completed for the entire duct / conduit run?	Yes	Refer to "WMATA Cheverly 6inch Power HH1 to HH2.avi"		
Was pull string installed?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	No	6" walker duct with less than 12 wires.		
Handhole 2 to Shared Trough (Distance: 15')				
Was video scoping completed for the entire duct / conduit run?	Yes	Refer to "WMATA Cheverly Station Power HH2 to AFC Panel.avi"		
Was pull string installed?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	No	6" walker duct with less than 12 wires.		
Shared Trough to AFC Panel (Distance: 1')				
Was video scoping completed for the entire duct / conduit run?	No	Video scoping of conduits not required.		
Was pull string installed?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No			
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.	No	2" conduit with less than 8 wires.		
Observations / Issues / Next Steps				

- The total distance of existing power duct / conduit between the Kiosk and AFC Panel is 154'.
- Scanning was completed at this mezzanine.

Sign Off				
	GFP Representative	WMATA PRGM		
Name:	Mike Butler			
Signature:	M.Zur			
Date:	03/16/15			

Photo 1 – Mezzanine layout showing existing duct route.



Photo 2 – Close-up of Handhole 1 on mezzanine floor.




Photo 3 – Handhole 2 in Room C200.




Photo 4 – AFC Panel and shared trough in Room C205.

