

ELECTRICAL AND DATA CABLE INSTALLATION

for

Washington Metropolitan Area Transit Authority

Contract Number FQ17021

VOLUME 4

Mezzanine Inspection Reports Part 1b Green and Yellow Lines

November 13, 2016

Final Submission

WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY

	VOLUME 4	PAGE NO.
	MEZZANINE INSPECTION REPORTS	
	PART 1B	
	GREEN & YELLOW LINES	
	TABLE OF CONTENTS	
1	MIR_C09_CRYSTAL CITY_MZ045	3
2	MIR_C10_REAGAN NATIONAL AIRPORT (SOUTH MEZZ)_MZ046	9
3	MIR_C10_REAGAN NATIONAL AIRPORT (NORTH MEZZ)_MZ093	13
4	MIR_C10_REAGAN NATIONAL AIRPORT (MINI MEZZ)_MZ093M	
5	MIR_C12_BRADDOCK ROAD_MZ047	18
6	MIR_C13_KING STREET-OLD TOWN_MZ048	26
7	MIR_C13_KING STREET-OLD TOWN (NEW ENTRANCE)_MZ048M	
8	MIR_C13_KING STREET-OLD TOWN (NORTH MEZZ)_MZ112	38
9	MIR_C15_HUNTINGTON (NORTH MEZZANINE)_MZ050	44
10	MIR_C15_HUNTINGTON (SOUTH MEZZANINE)_MZ051	51
11	MIR_E01_MOUNT VERNON SQUARE_MZ070	55
12	MIR_E02_SHAW-HOWARD U (SOUTH MEZZANINE)_MZ071	63
13	MIR_E02_SHAW-HOWARD U (NORTH MEZZANINE)_MZ072	72
14	MIR_E03_U STREET (EAST MEZZANINE)_MZ073	81
15	MIR_E03_U STREET (WEST MEZZANINE))_MZ074	86
16	MIR_E05_GEORGIA AVENUE_MZ076	95
17	MIR_E07_WEST HYATTSVILLE_MZ077	102
18	MIR_E08_PRINCE GEORGE'S PLAZA_MZ078	108
19	MIR_E09_COLLEGE PARK_MZ079	115
20	MIR_E10_GREENBELT_MZ080	121
21	MIR_F02_ARCHIVES_MZ081	128
22	MIR_F03_L'ENFANT PLAZA (NORTH MEZZANINE)_MZ082	136
23	MIR_F04_WATERFRONT_MZ083	143
24	MIR_F05_NAVY YARD-BALLPARK (WEST MEZZANINE)_MZ105	150
25	MIR_F06_ANACOSTIA (NORTH MEZZANINE)_MZ085	155
26	MIR_F06_ANACOSTIA (SOUTH MEZZANINE)_MZ106	161
27	MIR_F07_CONGRESS HEIGHTS_MZ086	168
28	MIR_F08_SOUTHERN AVENUE_MZ107	175
29	MIR_F09_NAYLOR ROAD_MZ087	180
30	MIR F11 BRANCH AVENUE M7089	186

Mezzanine Inspection Report (Scoping) Date: 11/12/2014 Station Name: C09 Crystal City Mezzanine #: 045 Completed By: Dion Small

Summary

All scoping for upper and lower communication ducts in the faregate arrays was completed. Upper power duct faregate array was completely scoped, but the lower power duct faregate array was only partially scoped due to heavy dust and debris allowing approximately 20' of the 30' run to be scoped. Pull string was installed in upper and lower communication duct faregate arrays and in the power conduit run from the kiosk to AFC panel.

Scanning is not required at this mezzanine.

Scoping of Faregate Array(s)				
Task 6	Yes/No	Notes		
Communications Duct – Upper Faregate Array (5- G	ates)			
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Crystal City Upper 3inch Comm Duct Video.avi, WMATA Crystal City Upper 6inch Comm Duct Video.avi, and WMATA Crystal City Upper 6inch Comm Duct Video (2).avi files.		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No	Heavy dust and debris		
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	1"x3" duct; 10-15 wires; 27' run with a 60-degree bend about 5' from kiosk.		
Communications Duct - Lower Faregate Array (6 G	ates)			
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Crystal City Lower 3inch Comm Duct Video.avi and WMATA Crystal City Lower 6inch Comm Duct Video.avi files.		
Were pull strings installed at all faregates in the array?	Yes			
Were there any obstructions or blockages? Provide details of type and specific location.	No	Heavy dust and debris		
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	1"x6" duct; less than 10 wires; 30' run with a 60-degree bend about 5' from kiosk.		
Power Duct - Upper Faregate Array (5 Gates)				
Was video scoping completed for the entire duct run?	Yes	Refer to WMATA Crystal City Upper 6inch Power Duct Video.avi file.		
Were there any obstructions or blockages? Provide details of type and specific location.	No	Heavy dust and debris		
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	1"x6" duct; less than 10 wires; 27' run with a 60-degree bend about 5' from kiosk.		
Power Duct - Lower Faregate Array (6 Gates)				
Was video scoping completed for the entire duct run?	No	20' scoped from a 30' run. Refer to WMATA Crystal City Lower 6inch Power Duct Video.avi file.		
Were there any obstructions or blockages? Provide details of type and specific location.	Yes	Heavy dust and debris		
Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.	No	1"x6" duct; less than 10 wires; 30' run with a 60-degree bend about 5' from kiosk.		

Scoping of Power Duct - Kiosk to AFC Panel							
	Task	Yes/No		Notes			
Kiosk to Cable	Trough in room C206 (70' run)						
Was video sco conduit run?	ping completed for the entire duct /	N/A	Run is a 2	embedded conduit from kiosk to trough			
Was pull string installed?		Yes					
Were there any obstructions or blockages? Provide details of type and specific location.		No					
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.		No	2" conduit is empty				
Cable Trough in	n room C206 to AFC Panel (60' run)		T				
Was video scoping completed for the entire duct / conduit run?		N/A	Run is a 2" conduit from trough to AFC Panel				
Was pull string installed?		Yes					
Were there any obstructions or blockages? Provide details of type and specific location.		No					
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.		No	2" conduit contains less than 10 wires				
		Observation	ns / Issues	Next Steps			
risk of complica	ontain a lot off dirt and debris; which a ation of cable installation. onduit run between Kiosk and AFC			e video-scope recording. Ducts should be cleaned to reduce any y 130'.			
			Sign Off				
	GFP Representative			WMATA PRGM			
Name:	Dion Small						
Signature:	Pica MII						
Date:	11/13/14						

Photo #1 – C09 Crystal City: Power run from kiosk




Photo #2 – C09 Crystal City: Power run from kiosk into trough box in room C206



Photo #3 – C09 Crystal City: Trough box in room C206




Photo #4 – C09 Crystal City: Conduit in room C300



Photo #5 – C09 Crystal City: Run to AFC Panel





	Mezzanin	e Inspe	ection Report (Scoping)
Date: 11/12/2014 Station Name: C10 Reagan Air		irport South	Mezzanine #: 046	Completed By: Balkis Hassane
			Summary	
				nd lower faregate arrays. Pull string was successfully installed in conduit run from kiosk to AFC
No scanning require	ed at this mezzanine.			
		Sconing	of Faregate Array(s)	
	Task		Traiegate Array(3)	Notes
Communications D	uct – Upper Faregate Array (4 G	Yes/No ates)		Notes
	completed for the entire duct	Yes	Refer to WMATA Reag	an Airport C10 Upper Comm Video.avi file.
Were pull strings insarray?	stalled at all faregates in the	Yes		
Were there any obsidetails of type and s	tructions or blockages? Provide pecific location.	No		
	ity? Provide additional details as of ducts and number of wires.	No	3" and 6" ducts – less t	han 5 wires
Communications Du	uct - Lower Faregate Array (5 G	ates)		
Was video scoping run?	completed for the entire duct	Yes	Refer to WMATA Reag	an Airport C10 Lower Comm Video.avi file.
Were pull strings ins array?	stalled at all faregates in the	Yes		
Were there any obsidetails of type and s	tructions or blockages? Provide specific location.	No		
Is the duct at capaci about the dimension	ity? Provide additional details as of ducts and number of wires.	No	3" and 6" ducts – less t	han 10 wires
Power Duct - Upper	Faregate Array (4 Gates)			
Was video scoping run?	completed for the entire duct	Yes	Refer to WMATA Reag	an Airport C10 Upper Power Video.avi file.
Were there any obsidetails of type and s	tructions or blockages? Provide pecific location.	No		
	ity? Provide additional details so of ducts and number of wires.	No	3" and 6" ducts – less t	han 10 wires
Power Duct - Lower	Faregate Array (5 Gates)			
Was video scoping run?	completed for the entire duct	Yes	Refer to WMATA Reag	an Airport C10 Lower Power Video.avi file.
Were there any obsidetails of type and s	tructions or blockages? Provide pecific location.	No		

 $3\ensuremath{\text{"}}$ and $6\ensuremath{\text{"}}$ ducts – less than 10 wires

No

Is the duct at capacity? Provide additional details about the dimensions of ducts and number of wires.

Scoping of Power Duct - Kiosk to AFC Panel						
	Task	Yes/No		Notes		
Kiosk to AFC Par	nel (120' run)					
Was video scopii conduit run?	ng completed for the entire duct /	No	Conduit –	no scoping required		
Was pull string installed?		Yes				
Were there any obstructions or blockages? Provide details of type and specific location.		No				
Is the duct / conduit at capacity? Provide additional details about the dimensions of duct / conduit and number of wires.		No	2" conduit – less than 10 wires			
		ı	ı			
	Observations / Issues / Next Steps					
A conduit passes through a 90 degree vertical bend at kiosk and is assumed to run along a straight path underground to connect with the AFC panel through another vertical 90 degree bend.						
No As-Built available for this mezzanine.						
Total conduit run from kiosk to AFC panel is 120'						
Sign Off						
	GFP Representative			WMATA PRGM		
Name:	Balkis Hassane			_		
Signature:	41					
Date:	11/12/2014					

Photo #1 – C10 Reagan Airport South: Existing conduit run from Kiosk towards AFC Panel

